



Z1900, Z1901, Z1902 Full Grate						
Item No.	Please Check	Grate Rim Thickness	Grate Open Area Sq. In.	Part Number		
1		1/2	31	29601-001		



<b>Z1900, Z1901, Z1902</b> <b>Suffix -2</b> Half Grate						
Item No.	Please Check	Grate Rim Thickness	Grate Open Area Sq. In.	Part Number		
2		1/2	42	29601-003		


	Suffix	, <b>Z1901,</b> -3 Quarter			
	Item No.	Please Check ✔	Grate Rim Thickness	Grate Open Area Sq. In.	Part Number
	3		1/2	36	29601-002
·					



Form # FS4 Date: 8/10/11 C.N. No. 121881 Rev. D Page 1 of 15 ZURN INDUSTRIES, LLC. ♦ SPECIFICATION DRAINAGE OPERATION ♦ 1801 Pittsburgh Ave. ♦ Erie, PA 16514 Phone: 814\455-0921 Fax: 814\454-7929 World Wide Web: www.zurn.com In Canada: ZURN INDUSTRIES LIMITED 🛭 3544 Nashua Drive 🔶 Mississauga, Ontario L4V1L2 🔶 Phone: 905/405-8272 Fax: 905/405-1292



# **Replacement Grates & Covers**



<b>Z1900, Z1901, Z1902</b> <b>Suffix -4</b> Full Grate w/ Round Center Opening						
Item No.	Please Check	Grate Rim Thickness	Grate Open Area Sq. In.	Part Number		
4		1/2	33	29601-005		

	-
-	9 SQ. —


7 <sup>1</sup> / <sub>2</sub>	$\begin{vmatrix} & & \\ & $
	SQ.

Suffix	-	<b>Z1902</b> et Cover	
ltem No.	Please Check	Cover Rim Thickness	Part Number
5		3/16	54252-001


<b>Z1900, Z1901, Z1902</b> <b>Suffix -16</b> Half Solid Loose Set Cover						
Item No.	Please Check	Cover Rim Thickness	Cover Open Area Sq. In.	Part Number		
6		3/16	26	54252-003		

Form #FS4Date:8/10/11C.N. No.121881Rev.DPage 2 of 15ZURN INDUSTRIES, LLC. • SPECIFICATION DRAINAGE OPERATION • 1801 Pittsburgh Ave. • Erie, PA 16514<br/>Phone:Phone:814\455-0921 • Fax:814\454-7929 • World Wide Web:www.zurn.comIn Canada:ZURN INDUSTRIES LIMITED • 3544 Nashua Drive • Mississauga, Ontario L4V1L2 • Phone:905\405-8272 Fax:905\405-1292





<b>Z1900, Z1901, Z1902</b> <b>Suffix -17</b> Three Quarter Solid Loose Set Cover					
ltem No.	Please Check	Cover Rim Thickness	Cover Open Area Sq. In.	Part Number	
7		3/16	12	54252-002	



Suffix	<b>Z1900, Z1901, Z1902</b> <b>Suffix -18</b> Loose Set Cover w/ Square Center Opening						
Item No.	Please Cover Cover Open Part Check Rim Area Number ✓ Thickness Sq. In.						
8		3/16	5	54252-004			


Form # FS4 Date: 8/10/11 C.N. No. 121881 Rev. D Page 3 of 15



12 SQ. \_

# Z1900, 1901, 1902 & ZN1900, ZN1901, ZN1902

**Replacement Grates & Covers** 




	ZN1900, ZN1901, ZN1902 Full Grate (May 1970 - March 2003)						
Item No.	Please Check	Grate Rim Thickness	Grate Open Area Sq. In.	Part Number			
9		7/32	27	51228-001			

	- - - - - - - - - - - - - - - - - - -
⊨ 12 SQ, — ►	

	ZN1900, ZN1901, ZN1902 Full Grate (March 2003 - August 2008)					
Item No.	Please Check	Grate Rim Thickness	Grate Open Area Sq. In.	Part Number		
10		3/8	25	67107-001		

ZN1900, ZN1901, ZN1902 Full Grate (August 2008 - Present)					
ltem No.	Please Check	Grate Rim Thickness	Grate Open Area Sq. In.	Part Number	
11		3/8	44	67107-001	



1<u>3</u> 16

 $\int_{1}^{1}$ 

4


In Canada: ZURN INDUSTRIES LIMITED ♦ 3544 Nashua Drive ♦ Mississauga, Ontario L4V1L2 ♦ Phone: 905\405-8272 Fax: 905\405-1292



Ø

 $5\frac{1}{32}$ 

**Replacement Grates & Covers** 




<b>ZN1900, ZN1901, ZN1902</b> <b>Suffix -2</b> (May 1970 - March 2003) Half Grate							
Item Please Grate Grate Open Part No. Check Rim Area Number ✓ Thickness Sg. In.							
12							

	- - - - 2 SQ. - -
• 12 SQ	

<b>ZN1900, ZN1901, ZN1902</b> <b>Suffix -2</b> (March 2003 - August 2008) Half Grate					
Item No.	Please Check ✓	Grate Rim Thickness	Grate Open Area Sq. In.	Part Number	
13		3/8	44	67107-005	

<b>ZN1900, ZN1901, ZN1902</b> <b>Suffix -2 (August 2008 - Present)</b> Half Grate				
ltem No.	Please Check	Grate Rim Thickness	Grate Open Area Sq. In.	Part Number
14		3/8	74	67107-005



 $\frac{13}{16}$ 


ł

12


ZURN INDUSTRIES, LLC. ♦ SPECIFICATION DRAINAGE OPERATION ♦ 1801 Pittsburgh Ave. ♦ Erie, PA 16514 Phone: 814\455-0921 ♦ Fax: 814\454-7929 ♦ World Wide Web: www.zurn.com In Canada: ZURN INDUSTRIES LIMITED ♦ 3544 Nashua Drive ♦ Mississauga, Ontario L4V1L2 ♦ Phone: 905\405-8272 Fax: 905\405-1292



#### **Replacement Grates & Covers**




<b>ZN1900, ZN1901, ZN1902</b> <b>Suffix -3</b> (May 1970 - March 2003) Three Quarter Grate					
Item No.	Please Check	Grate Rim Thickness	Grate Open Area Sq. In.	Part Number	
15		7/32	33	51228-003	



 $5\frac{1}{32}$  SQ.

<b>ZN1900, ZN1901, ZN1902</b> <b>Suffix -3</b> (March 2003 - August 2008) Three Quarter Grate					
ltem No.	Please Check	Grate Rim Thickness	Grate Open Area Sq. In.	Part Number	
16		3/8	34	67107-003	

<b>ZN1900, ZN1901, ZN1902</b> <b>Suffix -3</b> (August 2008 - Present) Three Quarter Grate				
Item No.	Please Check	Grate Rim Thickness	Grate Open Area Sq. In.	Part Number
17		3/8	58	67107-003




2


In Canada: ZURN INDUSTRIES LIMITED ♦ 3544 Nashua Drive ♦ Mississauga, Ontario L4V1L2 ♦ Phone: 905\405-8272 Fax: 905\405-1292



#### **Replacement Grates & Covers**




<b>ZN1900, ZN1901, ZN1902</b> <b>Suffix -4</b> (May 1970 - March 2003) Full Grate w/ Square Center Opening				
Item No.	Please Check	Grate Rim Thickness	Grate Open Area Sq. In.	Part Number
18		7/32	30	51228-007




In Canada: ZURN INDUSTRIES LIMITED ♦ 3544 Nashua Drive ♦ Mississauga, Ontario L4V1L2 ♦ Phone: 905\405-8272 Fax: 905\405-1292



### **Replacement Grates & Covers**








<b>ZN1900, ZN1901, ZN1902</b> <b>Suffix -12</b> (December 1972 - October 2003) Depressed Aluminum Grate				
ltem No.	Please Check	Grate Rim Thickness	Grate Open Area Sq. In.	Part Number
24		7/32	15	52060-001


<b>ZN1900, ZN1901, ZN1902</b> <b>Suffix -12 (October 2003 - Present)</b> Depressed Aluminum Grate				
Item No.	Please Check	Grate Rim Thickness	Grate Open Area Sq. In.	Part Number
25		3/8	15	67414-001

Form # FS4 Date: 8/10/11 C.N. No. 121881 Rev. D Page 9 of 15






ZN1900, ZN1901, ZN1902 Suffix -15 (June 1966 - November 2003) Solid Loose Set Cover				
Item Please Cover Part No. Check Rim Number ✓ Thickness				
26		3/16	46894-001	




ZN1900, ZN1901, ZN1902 Suffix -15 (November 2003 - Present) Solid Loose Set Cover					
Item Please No. Check		Cover Rim Thickness	Part Number		
27		3/8	67421-001		

Form # FS4 Date: 8/10/11 C.N. No. 121881 Rev. D Page 10 of 15







 - 4 <u>23</u> - 9 <u>25</u> - 9 <u>32</u>	
	SQ


<b>ZN1900, ZN1901, ZN1902</b> <b>Suffix -16 (June 1966 - November 2003)</b> Half Solid Loose Set Cover						
ItemPleaseCoverCover OpenPartNo.CheckRimAreaNumber✓ThicknessSq. In.						
28		3/16	35	46894-003		

<b>ZN1900, ZN1901, ZN1902</b> <b>Suffix -16 (November 2003 - October 2008)</b> Half Solid Loose Set Cover						
ltem No.	Please Check	Cover Rim Thickness	Cover Open Area Sq. In.	Part Number		
29		3/8	31	67421-005		

ZN1900, ZN1901, ZN1902 Suffix -16 (October 2008 - Present) Half Solid Loose Set Cover					
ItemPleaseCoverCover OpenPartNo.CheckRimAreaNumber✓ThicknessSq. In.					
30		3/8	46	67421-005	

Form #FS4Date:8/10/11C.N. No.121881Rev.DPage 11 of 15ZURN INDUSTRIES, LLC. • SPECIFICATION DRAINAGE OPERATION • 1801 Pittsburgh Ave. • Erie, PA 16514<br/>Phone:Phone:814\455-0921 • Fax:814\454-7929 • World Wide Web:www.zurn.comIn Canada:ZURN INDUSTRIES LIMITED • 3544 Nashua Drive • Mississauga, Ontario L4V1L2 • Phone:905\405-8272 Fax:905\405-1292





ZN1900, ZN1901, ZN1902 Suffix -17 (June 1966 - November 2003) Three Quarter Solid Loose Set Cover						
ltem No.	Please Check	Cover Rim Thickness	Cover Open Area Sq. In.	Part Number		
31		3/16	18	46894-005		

<b> </b>
----------

- 4 <sup>23</sup> / <sub>32</sub> SQ	
<b>–</b> 12	'SQ. —

Form # FS4

	<b>ZN1900, ZN1901, ZN1902</b> <b>Suffix -17</b> (November 2003 - October 2008) Three Quarter Solid Loose Set Cover					
ItemPleaseCoverCover OpenPartNo.CheckRimAreaNumbe✓ThicknessSq. In.						
	32		3/8	15	67421-003	

ZN1900, ZN1901, ZN1902 Suffix -17 (October 2008 - Present) Three Quarter Solid Loose Set Cover					
ltem No.	Please Check ✓	Cover Rim Thickness	Cover Open Area Sq. In.	Part Number	
33		3/8	22	67421-003	

Page 12 of 15


Rev. D

ZURN INDUSTRIES, LLC. ♦ SPECIFICATION DRAINAGE OPERATION ♦ 1801 Pittsburgh Ave. ♦ Erie, PA 16514 Phone: 814\455-0921 ♦ Fax: 814\454-7929 ♦ World Wide Web: www.zurn.com In Canada: ZURN INDUSTRIES LIMITED ♦ 3544 Nashua Drive ♦ Mississauga, Ontario L4V1L2 ♦ Phone: 905\405-8272 Fax: 905\405-1292

**C.N. No.** 121881

**Date:** 8/10/11





ZN1900, ZN1901, ZN1902							
Suffix	-18 (Ju	ne 1966 - I	November 20	003)			
Loose	Set Cov	er w/ Squa	re Center O	pening			
Item Please Cover Cover Open Part							
No.	Check	Rim	Area	Number			
	$\checkmark$	Thickness	Sq. In.				
34		3/16	9	46894-007			

_	
	┝━──── 12 SQ. ────

_		
1	<b>–</b> 12	SQ. ———

Form # FS4

ZN1900, ZN1901, ZN1902 Suffix -18 (November 2003 - October 2008) Loose Set Cover w/ Square Center Opening						
ltem No.	Please Check	Cover Rim Thickness	Cover Open Area Sq. In.	Part Number		
35		3/8	9	67421-007		

ZN1900, ZN1901, ZN1902 Suffix -18 (October 2008 - Present) Loose Set Cover w/ Square Center Opening					
ltem No.	Please Check	Cover Rim Thickness	Cover Open Area Sq. In.	Part Number	
36		3/8	9	67421-007	

Page 13 of 15

Rev. D


ZURN INDUSTRIES, LLC. ♦ SPECIFICATION DRAINAGE OPERATION ♦ 1801 Pittsburgh Ave. ♦ Erie, PA 16514 Phone: 814\455-0921 ♦ Fax: 814\454-7929 ♦ World Wide Web: www.zurn.com In Canada: ZURN INDUSTRIES LIMITED ♦ 3544 Nashua Drive ♦ Mississauga, Ontario L4V1L2 ♦ Phone: 905\405-8272 Fax: 905\405-1292

**C.N. No.** 121881


**Date:** 8/10/11



**Replacement Grates & Covers** 




ZN1900, ZN1901, ZN1902 Suffix -19 (February 1961 - January 2003) Full Hinged Grate					
Item No.	Please Check	Grate Rim Thickness	Grate Open Area Sq. In.	Part Number	
37		5/32	40	33159-001	




<b>ZN1900, ZN1901, ZN1902</b> <b>Suffix -19 (January 2003 - Present)</b> Full Hinged Grate					
Item No.	Please Check ✔	Grate Rim Thickness	Grate Open Area Sq. In.	Part Number	
38		3/8	25	66669-001	

Form # FS4 Date: 8/10/11 C.N. No. 121881 Rev. D Page 14 of 15





ZN1900, ZN1901, ZN1902 Suffix -HP (January 1998 - October 2003) Heel-Proof Grate					
ltem No.	Please Check ✔	Grate Rim Thickness	Grate Open Area Sq. In.	Part Number	
39		3/16	12	980104-1	



Suffix	<b>ZN1900, ZN1901, ZN1902</b> <b>Suffix -HP (October 2003 - Present)</b> Heel-Proof Grate					
Item No.	Please Check	Grate Rim Thickness	Grate Open Area Sq. In.	Part Number		
40		3/8	18	67416-001		

Form # FS4 Date: 8/10/11 C.N. No. 121881 Rev. D Page 15 of 15